CONTRACT INSP. JON REPORT			CONTRACT NO.	TASK NO.				
то:		INSPECTION REPORT NO. (If final, so state)						
		ESTIMATED COMPLETION DATE						
NAME OF CONTRACTOR					· · · · · · · · · · · · · · · · · · ·			
			Declass Review by NGA.					
TYPE OF COMMODITY OR SERVICE	int ?	able vi	in Howet for Verlous	Miorost	Arabito	**		
THE CONTRACTOR IS ON SCHEDULE YES NO			THE CONTRACTOR WILL PROBABLY REMAIN WITHIN ALLOCATED FUNDS YES NO IF ANSWER IS "NO" ADVISE RECOMMENDATION AND/OR ACTION OF SPONSORING OFFICE, ON REVERSE HEREOF. IF KNOWN, INDICATE MAGNITUDE OF ADDITIONAL FUNDS INVOLVED.					
PER CENT OF WORK COMPLETED								
HAS AN INTERIM REPORT, FINAL DURING THE PERIOD? THE PROPERTY HAS GOVERNMENT-OWNED PROPERTY	O (If Been de	yes, give LIVERED TO	details on reverse side.) CONTRACTOR DURING THIS P		M THE CON	TRACTOR		
(If yes, indicate items, quantity,	and cos	·····	se side.)					
IS THIS AN INCENTIVE CONTRACT IF YES, CHECK TYPE COST AWARD PERFORMANC		¥□ NO	NOTE: USE REVERSE SIDE FOR COM FINAL REPORT MUST CONTAI		E EVALUATI	ON.		
			ICE OF CONTRACTOR					
1. OUTSTANDING 4.	AI	BOVE AVERA	GE 7. UNSATISF	ACTORY				
2. EXCELLENT 5	· 🔲 🗛	VERAGE						
3. VERY GOOD IF OVERALL PERFORMANCE OF COM REASONS ON REVERSE SIDE.	~ `—	INIMUM ACC		TABLE INDIC	ATE			
		RECOMMEN	ED ACTION					
CONTINUE AS PROGRAMMED			withhold Payment P Satisfactory Perfo					
CLOSE OUT			OTHER (Specify)					
IF THIS IS A FINAL REPORT PUT AND CERTIFY THAT ALL DELIVERABLE OF APPLICABLE, THE FOLLOWING:								
ITEM	REC'D	DOES NOT APPLY	ITEM		REC'D	DOES NOT		
<u>,</u>		1	MANUALS					
PROTOTYPES		<u> </u>	FINAL REPORT		 			
DRAWINGS AND SPECIFICATIONS		1	SPECIAL TOOLING OTHER GOVERNMENT PROPERTY					
			OTHER GOVERNMENT PROPERT	Y				
PRODUCTION AND/OR OTHER END ITEMS			OTHER GOVERNMENT PROPERT	Υ		<u> </u>		
DRAWINGS AND SPECIFICATIONS PRODUCTION AND/OR OTHER			OTHER GOVERNMENT PROPERT	Y				

25X1

25X1

Approved For Release 2005/05/02 : CIA-RDP78B04770A002200040022-1

SECRET		CONF ID			
NAI	RRATIVE REPORT		X INTER	IM	FINAL
	otype light tab	in waneiwa	a sa	on 2/6/6	5 9.
1. Prov	omine Trene can	TO EMPERIMENT	And house		
2. Oper	ating and maint o be received.	edance mu	date and other		
did little or	ormince of cont no werk on the ary of the prot of the leatring	Constage	than was ando	o complete	
	light tools is			. V	
5. Door	site the poor particular deli- m delivered va-	erformater err exter	of the Contract	tor with re quality of	spect the
•					
	en e				
		· · · · · · · · · · · · · · · · · · ·			
				- · ·	
	·				
			•	•	
•				* • •	
					·
		1 2 3 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	,		
· .	1.				
	. •				•
			* **	· · · · ·	
* 130		1. 1. 3.		6 1	

FAULTS DISCOVERED IN 1540 LIGHT TABLE

- l. Light flicker both sides
- 2. Film take-up mechanism slips (Corrected)
- 3. Wrong direction on switch for right mear film drive (Corrected)
- 4. Slip clutch /-direction carriage noisy
- 5. Elevating mechanism vibrates during lowering of table
- 6. Elevating mechanism lifts unevenly
- 7. Minimum light level approximately 150 foot lamberts and not 75
- 8. Detents sloppy
- 9. Light gradient excessive

PRELIMINARY COMMENTS ON 1540 LIGHT TABLE

Film Drive:

Nice - different feel, but PI will like once he becomes accustomed to it.

Prefer mechanical hand crank because of more precise control.

Can't scan with crank.

Crank rough at slow speed.

Add lock on film null position - perhaps by pulling out on film speed control knob.

Carriage (Optics) Drive:

The PI should really like this.

Unnecessary

Drive motor noisy

Switch handle too short

Use push button rather than bat-handle switch

Approved For Release 2005/05/02: CIA-RDP78B04770A002200040022-1

Table Elevation:

Motorized table elevation unnecessary

Great

Lower limit of table height too high

Upper limit is fine - for various reasons

Wall Stand-offs:

Rub against wall when raising table.

Bumpers may put hole in wall--locate near baseboard.

Bumpers weak--make more rugged.

Controls:

Location very nice--have been human-factored.

Levers for opening tables get in way.

Make film take-up knob different from right film drive crank knob.

General:

Very nice table.

The Cadillac of light tables.

Perhaps there is a need for a less complicated table as a basic table, with options.

Coolant level tubes should be visible from front or sides.

Spare fuses unsightly -- enclose.

Use circuit breakers rather than fuses.

Enclose all drive chains

Add slack take-up device to drive chains.

Films rub together in split-vertical mode with tables closed.

Replace pan head screws on lower film reel guards with flat-head screws

Add limit switch or slip clutch on upward motion of focusing drive

Different clips on bottom panel of light bex.

Approved For Release 2005/05/02 : CIA-RDP78B04770A002200040022-1

For every negative comment, of course, there were several others who looked at the same things and found no fault.